

DTR Survey Mis-Matches:

As part of the Smart Meters Installation project, M/s AESL surveyed Distribution Transformers. Upon reviewing the AESL survey data, certain mismatches were observed. The following screen has been developed in the EPCCB and made available in the AE-Operation's login to address these discrepancies.

Path: Smart Meters >> Smart Metering >> DTR Survey Mis-Matches

DTR STRUCTURE CODE	DTR LOCATION	FEEDER CODE			CAPACITY			PHASE	
		EPCCB	AESL	REASON	EPCCB	AESL	REASON	EPCCB	AESL
034500133143	SS-326, BHARGAVI ENCLAVE	03142101	03142101		63	100	SELECT	3	3 PH
034500133089	GAVDHI BHAVAN,SS206	03142106	03142106		63	100	SELECT	3	3 PH
034500130124	SS297 near 34A,5	03142101	03142101		40	63	SELECT	3	3 PH
034500132014	SARSWATHI NILYAM, NR 293 A 3	03142101	03142101		40	63	SELECT	3	3 PH

Wherever a mismatch is identified, a dropdown is provided with the following options:

a) **AESL – Needs to Correct**

b) **APEPDCL – Needs to Correct**

- If **AESL – Needs to Correct** is selected, the data is sent to AESL for re-survey.
- If **APEPDCL – Needs to Correct** is selected, the data is to be updated in SAP and OMS.

SL No.	DTR STRUCTURE CODE	DTR LOCATION	FEEDER CODE			CAPACITY			PHASE			ACTION
			EPCCB	AESL	REASON	EPCCB	AESL	REASON	EPCCB	AESL	REASON	
1	034500133143	SS-326, BHARGAVI ENCLAVE	03142101	03142101		63	100	SELECT	3	3 PH	SELECT	submit
2	034500133089	GAVDHI BHAVAN,SS206	03142106	03142106		63	100	SELECT	3	3 PH	SELECT	submit
3	034500130124	SS297 near 34A,5	03142101	03142101		40	63	SELECT	3	3 PH	SELECT	submit
4	034500132014	SARSWATHI NILYAM, NR 293 A 3	03142101	03142101		40	63	SELECT	3	3 PH	SELECT	submit
5	034500132042	NEAR SS 152 RAZIA	03142106	03142106		25	63	SELECT	3	3 PH	SELECT	submit
6	034500133029	SIDDHARTHA TOWERS	03142106	03142106		100	63	SELECT	3	3 PH	SELECT	submit
7	034500133077	CHETTIABU CLNY SS190	03142101	03142101		100	180	SELECT	3	3 PH	SELECT	submit